

# Geological Survey Daily Field Activity Report

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
Alex Code 3/3/2014 to  
Oil and Gas (615) Activities Lease Inspection On-Site Inspection Oil Well Producing  
Well leaking at packing into secondary containment. Containment has not overflowed yet, but leak needs to be addressed and secondary pumped.

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
William Duley 2/27/2013 1:05 PM to 1:20 PM  
Oil and Gas (615) Activities Rework On-Site Inspection Oil Well Producing  
Beckman Rig # 5 is on site. Work over acid job is in progress. Bert Molina is the onsite Merit person. Liners and berms not properly placed under the rig, around the wellhead and under the piperack. Will contact Merit w/ concerns.

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
William Duley 8/26/2011 2:06 PM to 2:07 PM  
Oil and Gas (615) Activities Lease Inspection On-Site Inspection Oil Well Producing  
Unit is pumping. 180 psi no obvious leaks or violations

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
William Duley 4/20/2010 12:10 PM to 12:12 PM  
Oil and Gas (615) Activities Lease Inspection On-Site Inspection Oil Well Producing  
0 psi tubing pressure Unit not currently pumping. No obvious leaks or violations

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
Jeff Dexter 8/1/2008 to  
Oil and Gas (615) Activities Lease Inspection On-Site Inspection Oil Well Producing  
No violations observed.

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
Jeff Dexter 11/14/2007 to  
Oil and Gas (615) Activities Lease Inspection On-Site Inspection Oil Well Producing  
No violations observed.

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
Jeff Dexter 6/4/2006 to  
Oil and Gas (615) Activities Lease Inspection On-Site Inspection Oil Well Producing  
No violations observed.

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
Jeff Dexter 8/4/2005 12:50 PM to  
Oil and Gas (615) Activities Lease Inspection On-Site Inspection Oil Well Producing  
No violations observed.

---

# Geological Survey Daily Field Activity Report

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
Jeff Dexter 8/26/2004 12:50 PM to 12:53 PM  
Oil and Gas (615) Activities Lease Inspection On-Site Inspection Oil Well Producing  
No violations observed.

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
Jeff Dexter 12/11/2003 11:52 AM to 11:55 AM  
Oil and Gas (615) Activities Transfer of Owner On-Site Inspection Oil Well Producing  
No violations-o.k. to transfer.

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
Jeff Dexter 5/30/2003 11:12 AM to 11:15 AM  
Oil and Gas (615) Activities Lease Inspection On-Site Inspection Oil Well Producing  
No permit number posted on identification sign.  

<u>Violation</u>	<u>Rule#/Description</u>
Y	08. R1012 Identification sign posted at the wellhead

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
Jeff Dexter 7/17/2002 11:45 AM to 11:48 AM  
Oil and Gas (615) Activities Lease Inspection On-Site Inspection Oil Well Producing  
No violations observed.

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
Jeff Dexter 6/27/2001 11:20 AM to 11:24 AM  
Oil and Gas (615) Activities Lease Inspection On-Site Inspection Oil Well Producing  
No violations observed.

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
Jeff Dexter 4/17/2001 1:30 PM to 1:45 PM  
Oil and Gas (615) Activities Rework On-Site Inspection Oil Well Producing  
Halliburton on location to acidize existing perfs in this Niagaran well.

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
Jeff Dexter 8/22/2000 12:32 PM to 12:35 PM  
Oil and Gas (615) Activities Lease Inspection On-Site Inspection Oil Well Producing  
No violations observed.

---

# Geological Survey Daily Field Activity Report

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
Virgil Lopez 6/7/2000 1:00 PM to 1:15 PM  
Oil and Gas (615) Activities Lease Inspection On-Site Inspection Oil Well Producing  
(1) Casing valve and rams should be colored yellow.  

<u>Violation</u>	<u>Rule#/Description</u>
Y	11. R1119 H2S, Yellow valves necessary to shut off all fluid flow at the wellhead.

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
Virgil Lopez 2/2/2000 10:30 AM to 10:45 AM  
Oil and Gas (615) Activities Lease Inspection On-Site Inspection Oil Well Producing  
Ground snow covered - site OK

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
Jeff Dexter 8/3/1999 1:35 PM to 1:38 PM  
Oil and Gas (615) Activities Lease Inspection Not Available Not Available Not Available  
Lease inspection-no problems.

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
Virgil Lopez 2/3/1999 11:30 AM to 12:00 PM  
Oil and Gas (615) Activities Lease Inspection Not Available Not Available Not Available  
(1) Master valve to shut in well should be yellow  
(2) Flowline route marker not readily located

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
Jeff Dexter 7/13/1998 1:17 PM to 1:20 PM  
Oil and Gas (615) Activities Lease Inspection Not Available Not Available Not Available  
Lease inspection-no problems. Confidential = F Inspection = T

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
12/31/1997 12:00 PM to 12:01 PM  
1997 AWSUM Report Oil Well Producing

---

40134 WOOD 5-11 CRAWFORD  
MERIT ENERGY CO  
Jeff Dexter 3/28/1996 1:30 PM to 1:35 PM  
Oil and Gas (615) Activities Lease Inspection Not Available Not Available Not Available  
Lease inspection-no problems. Confidential = F Inspection = T

---

# Geological Survey Daily Field Activity Report

---

40134 WOOD 5-11

CRAWFORD

MERIT ENERGY CO

9/29/1989 to

Oil and Gas (615) Activities Miscellaneous / Other Not Available Not Available Not Available

REQUEST T.A. STATUS/THIS WELL IS IN WATER FLOOD & WILL BE HELD AS A OBSERVATION - MONITOR  
WELL FOR POTENTIAL PATTERN CHANGES Confidential = Inspection =

---

40134 WOOD 5-11

CRAWFORD

MERIT ENERGY CO

11/9/1988 to

Oil and Gas (615) Activities Miscellaneous / Other Not Available Not Available Not Available

PLUG BK EXIS PERFS/RUN PROD EQUIPMENT AND FLANGE WELL UP/PERF/ACIDIZE/SWAB WELL TO CLEAN  
UP/PLACE ON PRODUCTION Confidential = Inspection =

---

40134 WOOD 5-11

CRAWFORD

MERIT ENERGY CO

12/26/1986 to

Oil and Gas (615) Activities Miscellaneous / Other Not Available Not Available Not Available

CIRC. & CONDITION HOLE CIRC. CEMENT & PLUGAT 6675 PULL BACK & CIC. CEMENT INSTALL TEMP. WELL  
HEAD HOLD T.A. FOR RE-ENTRY Confidential = Inspection =

---